Idaho PUC Pipeline Safety Inspection Summary

Inspector(s): Russo / Perkins			Date(s):	2-Jan-20
Company/Owner: Intermountain Gas Company Unit/OPID: 8160				
Company/ Owner.	Intermot	antain das company	Offic, OPID.	8100
Inspection Type & Time (1 day)	Total Ir	spection Days:	2
Standard: Construction: 2 Training: (T)(D) Integrity Management: Incident:				
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
Observed a Dasco crew installing a new service with an EFV. They used proper bedding and shading procedures and left a stub and stub marker for the future property next door. Pressure tested the service and tied it in. Typed up report Areas observed during this project were: Excavating, Line locating, Pressure testing, Backfilling				
Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.				
Corrective Action Required:	Follo	w-up Required: Yes	No	Х
Yes No		wap nequired. 185	by (date):	^_
Inspector (Lead):	1		Date:	
Kyle Russo	#15	Jan 100	1/2/2020	
Reviewer:	Jam III		Date:	Jan 2020